

POPPLETON HISTORIC STUDY

b-2666  
MAG#0426665704

<u>Block</u>	<u>Lot</u>	<u>Address</u>
233	18-25	29-45 S. Carey Street

Approximate age

<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
		29-41		43/45 (1906)

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>			
A	Significant-save	good	fair	poor	bad
(B)	Quality-Indiv./groups-save	(good)	fair	poor	bad 43/45
(C)	Important to street/groups	good	fair	(poor)	bad
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:

A row of gable roofed houses stood here in 1868. Rebuilding a possibility in the 1870's. All are low, with no steps or low steps, many segmental window arches. An undistinguished but dignified row of houses, severe lines and details. They should be rehabilitated.


The fire station is a good looking building with nice iron work.

Environmental context:

Has one very good street tree; could use more; houses across-street in worst condition but scale is compatible and street is tolerable from traffic point of view.



Sanborn Maps



B-2666  
29-45 South Carey Street  
Block 233 Lots 018-025  
Baltimore City  
Baltimore West Quad.

